



Table of Contents

Volume 2a: Figures

Figure 1.1 - Site Location Plan

Figure 1.2 - Site Boundary

Figure 1.3 - Proposed Development Layout

Figure 2.1 - Combined Constraints and Infrastructure Layout

Figure 3.1 - Indicative Wind Turbine Details

Figure 3.2a - Indicative Wind Turbine Gravity Foundation

Figure 3.2b - Indicative Wind Turbine Piled Foundation

Figure 3.3 - Typical Crane Hardstand

Figure 3.4a - Typical Access Track

Figure 3.5 - Indicative Site Entrance Layout

Figure 3.6 - Indicative AIL Access Route

Figure 3.7a-d - Typical Drainage Details

Figure 3.8a-b - Typical Water Crossing Types

Figure 3.9a - Indicative Substation Compound Layout

Figure 3.9b - Indicative Substation Compound Elevation

Figure 3.10 - Typical Telecommunications Mast

Figure 3.11a-b - Indicative BESS Layout and Elevations

Figure 3.12 - Typical Cable Trench Details

Figure 3.13 - Typical Temporary Construction Compound

Figure 3.14a-d - Indicative Borrow Pits General Arrangement

Figure 3.15 - Typical Batching Plant Layout

Figure 5.1 - Study Area

Figure 5.2 - Landform

Figure 5.3a-c - Landscape Character Plans

Figure 5.4 - Landscape Designations and Wild Land Areas

Figure 5.5 - Principal Visual Receptors

Figure 5.6a-d - Blade Tip ZTV with VPs

Figure 5.7a-d - Hub Height ZTV with VPs

Figure 5.8 - Horizontal Angle ZTV

Figure 5.9a-d - Landscape Character and ZTVs

Figure 5.10a-b - Landscape Designations with ZTVs

Figure 5.10c - Wild Land Areas with ZTV

Figure 5.11a-b - Principal Visual Receptors with ZTVs

Figure 5.12 - Cumulative Wind Farms

Figure 5.13a-j - Cumulative ZTVs

Figure 5.14 - Baseline Light Pollution

Figure 5.15 - ZTV of Turbine Hub Lighting

Figure 5.16 - Hub Lighting Intensity ZTV

Figure 6.1-6.1i - Gazetteer Assets

Figure 6.2 - Heritage Designations

Figure 6.3 - Heritage Viewpoints and ZTV

Figure 6.4a-f - Viewpoint 1 Edinchat Cairn

Figure 6.5a-i - Viewpoint 2 Banchar Cairn

Figure 6.6a-i - Viewpoint 3 Dalarossie Cottage Cairn

Figure 6.7a-f - Viewpoint 4, Woodend Cairn

Figure 6.8a-f - Viewpoint 5, Kyllachy Hill Cairn

Figure 6.9a-d - Viewpoint 6, Drumbain Cottage

Figure 6.10a-d - Viewpoint 7, Soilsean

Figure 7.1 - Site Context and Designations

Figure 7.2a-e - Extended Phase 1 Survey

Figure 7.3a-e - UKHAB Survey Results

Figure 7.4a-e - NVC Survey Results

Figure 8.1 - Designated Sites within 10km

Figure 8.2 - Vantage Point Locations and Viewsheds

Figure 8.3a-l - Breeding Bird Survey Results 2021

Figure 8.4a-l - Breeding Bird Survey Results 2022

Figure 8.5a - Breeding Bird Survey Results Meadow Pipit

Figure 8.5b - Breeding Bird Survey Results Other Species

Figure 9.1 - Local Hydrology

Figure 9.2 - Soil Map

Figure 9.3 - Superficial Geology

Figure 9.4 - Peatland Classification

Figure 9.5a-b - Bedrock Geology

Figure 9.6 - Regional Hydrogeology

Figure 9.7 - Groundwater Vulnerability

Figure 9.8 - Potential GWDTE

Figure 10.1 - Transport Assessment Study Area

Figure 10.2 - ATC Counter Locations

Figure 10.3 - Personal Injury Collision Locations

Figure 10.4 - Abnormal Load Route to Site

Figure 11.1 - Predicted Sound Footprint

Figure 11.2 - Predicted BESS Sound Footprint

Figure 12.1 - Aviation Lighting Scheme

Figure 12.2 - Shadow Flicker Assessment Area